

QC536001



**Specifications**

Input voltage & frequency	120V~60Hz
Output voltage	20V V
Charging time 2,0Ah battery	30mins
Charging time 2,5Ah battery	40mins
Charging time 4,0Ah battery	50mins
Charging time 5,0Ah battery	60mins
Tool Weight (pound)	1.58

**Long Description**

Get Powered Up FastCharge any SKIL 20VPWRCore™ Lithium battery in a flash with the SKIL PWRCore 20 Auto PWR JUMP Charger. Less charging time for batteries means less downtime, getting you back to the job faster. When you power up your tools with the SKIL 20V Charger, nothing can stand between you and getting the job done.

**Key Features**

- CHARGES IN 5 MINUTES— Auto PWR JUMP™ charges the battery in just 5 minutes, or 100% battery in 30 minutes (for 2.0Ah battery).
- ALWAYS KNOW CHARGE STATUS—Clear LED indicator lights show charge status.
- PWRCore 20 System—Pairs with any SKIL 20V battery.

**Packaging Contains**

PWRJUMP™ Charger;Manual;Warranty card

